

Annexure D

BUILDING SAFETY CERTIFICATE

Letter No.....931.....

Dated: 15/7/2025

It is certified that the existing building... **SACRED HEART SCHOOL, DUMKA**.... (Name of the building or premises) at **Opp. - LIC OFFICE, RAMPURHAT ROAD DUMKA-814101, JHARKHAND** (Address) is having lock(s)/Floor(s) as per details below:


Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No .of Floor(s) in the Block	G+2	G+2				

The building is owned /occupied by **SACRED HEART SCHOOL, DUMKA** (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **Junior Engineer/Assistant Engineer, Building Construction Department, Building Division, Dumka** (Name of Department /Govt.) On...**15-07-2025**... (Date of inspection) in the presence of **ANCY JOSEPH, (PRINCIPAL) SACRED HEART SCHOOL, DUMKA** (Name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from **15-07-2025** for a period of **2025-2026** years in accordance

Signature with Seal:

Designation: Executive Engineer

Name &Address of Department/Office: Building Division Dumka


15/7/2025
Executive Engineer
Building Division
Dumka